

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	es Present During the Inspection:
Company	Dave Shaver
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0070019			
Inspection Type:	PARTIAL			
Inspection Date:	Monday, April 18, 2011			
Start Date/Time:	4/18/2011 8:30:00 AM			
End Date/Time:	4/18/2011 12:00:00 PM			
Last Inspection:	Wednesday, March 09, 2011			

Inspector: Karl Houskeeper,

Weather: Overcast, Temp. 55 Deg. F. InspectionID Report Number: 2715

Accepted by: jhelfric 5/3/2011

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: CENTENNIAL MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

6,528.83	Total Permitted		
47.19	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership Types of Operations

✓ Federal

State

✓ Underground☐ Surface

 □ County
 □ Loadout

 ✔ Fee
 □ Processing

 □ Other
 □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl R. Housbupes

Date



Karl Houskeeper,

Permit Number: C0070019
Inspection Type: PARTIAL

Inspection Date: Monday, April 18, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives	✓		✓	
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	~			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	a Roads: Construction, Maintenance, Surfacing				
16.t	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070019
Inspection Type: PARTIAL

Inspection Date: Monday, April 18, 2011

Page 3 of 3

2. Signs and Markers

Mine identification sign in place at a point of public access into the permit area. The sign contains the required information.

4.a Hydrologic Balance: Diversions

The tree that traversed the upper main road diversion has been removed.

5. Explosives

Only the cap magazine remains on site. The explosive magazine has been removed.